

NOTE—These drawings, specifications, or other data (1) are, and remain the property of Amphenol Corporation (2) must be returned upon request; and (3) are confidential and are not to be disclosed to any person other than those to whom they are given by Amphenol Corporation. The furnishing of these drawings, specifications, or other data by Amphenol Corporation, or by any other person, to anyone for any purpose is not to be regarded by implication or otherwise as in any manner licensing, granting rights or permission, such holder or any other person to manufacture, use or sell any product, process or design, patented or otherwise, that may in any way be related to or disclosed by said drawings, specifications or other data.


AMPHENOL NORTH AMERICA, DANBURY, CONN.

REVISIONS


SYM.	DESCRIPTION	DATE	APPROVED
31	REDRAWN - ADDED SHEETS 25 & 26 SHEET 7 REVISED ECO 29676	12/22/82 BCK 29676	
32	ADD SHT 27 3-15-90 ECO 37121	3/12/90	27
33	REVISE SHEET 12 ECO 38009	3/12/91	AB
34	Remove 60/40 Solder Ref ECO 46001	3/29/90	CPM

NAME		DATE		<p style="text-align: center;">AMPHENOL • Danbury, Connecticut</p>	
PREP. BY J.A. HURBLE					
CHK. BY				<p style="text-align: center;">SPECIFICATION TITLE: ASSEMBLY PROCEDURES FOR TYPE SMA CONNECTORS.</p>	
PROJ. ENG.					
APPD. BY					
DATE ISSUED					
UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES: AND TOLERANCES ARE:		CODE IDENT.	SPECIFICATION No.		ISSUE
FRACTIONS	DECIMALS	ANGLES	349-5011A		34
$\pm \frac{1}{64}$	$\pm .005$	$\pm 1^\circ$	SCALE: NONE	SHEET 1	CONT. ON 2

ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-113




901-113 COMPLETE ASSEMBLY
(PLUG)




STRIPPING DIM'S SHOWN
FOR REF. ONLY


TOOLS REQ'D: KIT NO. 901-2500.




TRIM CABLE SQUARE, DEBURR AND CLEAN
COPPER JACKET 5/8 MIN.



USING TOOL 901-A AND RAZOR BLADE,
SCORE COPPER JACKET UNTIL BLADE
BOTTOMS IN TOOL. RETRACT CABLE TO
SCORE LINE. APPLY LIGHT BENDING
ALTERNATELY UNTIL COPPER JACKET
SEPARATES AT SCORE LINE AND REMOVE.





PLACE PLUG ASSEMBLY OVER CABLE;
COPPER JACKET MUST BOTTOM ON
SHOULDER OF BODY. SOLDER AS SHOWN.




CAUTION - BEFORE TRIMMING DIELECTRIC,
ASSEMBLY MUST BE ALLOWED TO COOL.
SLIDE COUPLING NUT BACK AGAINST
SOLDERING FLANGE. CUT DIELECTRIC
SQUARE AND AS CLOSE TO BODY AS
POSSIBLE AND REMOVE. DO NOT NICK
CENTER CONDUCTOR. FILE BLUNT END
OF CENTER CONDUCTOR TO A 90° CONE.

ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTORS


NOS. 901-105, -106, -141 & -157, -376, & 82-28




TRIM CABLE SQUARE, DEBURR & CLEAN
COPPER JACKET 5/8 MIN.




USING TOOL 901-A AND RAZOR BLADE, SCORE COPPER JACKET UNTIL BLADE BOTTOMS IN TOOL. RETRACT CABLE TO SCORE LINE. APPLY LIGHT BENDING FORCE ALTERNATELY UNTIL COPPER JACKET SEPARATES AT SCORE LINE AND REMOVE.




PLACE SOLDER NUT OVER CABLE; COPPER JACKET MUST BOTTOM ON SHOULDER OF SOLDER NUT. SOLDER AS SHOWN.




CAUTION - BEFORE TRIMMING DIELECTRIC, ASSEMBLY MUST BE ALLOWED TO COOL. USING DIELECTRIC TRIM TOOL 901-B AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE. DO NOT NICK CENTER CONDUCTOR.



SOLDER CENTER CONTACT TO CABLE. CENTER CONTACT MUST SEAT SQUARE AGAINST DIELECTRIC. AVOID EXCESSIVE HEAT WHICH MAY DISTORT DIELECTRIC.





REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY. INSTALL GASKET AS SHOWN.




THREAD CONNECTOR ASSEMBLY ONTO PREPARED CABLE ASSEMBLY. TIGHTEN TO 15-20 IN/LBS. TORQUE.


ASSEMBLY PROCEDURE FOR FIELD SERVICEABLE SMA CONNECTORS NOS. 901-107 & 901-108




TRIM CABLE SQUARE, DEBURR & CLEAN
COPPER JACKET 5/8 MIN.




USING TOOL 901-A AND RAZOR BLADE,
SCORE COPPER JACKET UNTIL BLADE BOTTOMS
IN TOOL. RETRACT CABLE TO SCORE LINE.
APPLY LIGHT BENDING FORCE ALTERNATELY
UNTIL COPPER JACKET SEPARATES AT
SCORE LINE AND REMOVE.




USING DIELECTRIC TRIM TOOL 901-C
AND RAZOR BLADE, REMOVE EXPOSED
DIELECTRIC. CUT MUST BE SQUARE.
DO NOT NICK CENTER CONDUCTOR.




SOLDER CENTER CONTACT TO CABLE,
CENTER CONTACT MUST SEAT SQUARE
AGAINST DIELECTRIC. AVOID EXCESSIVE
HEAT WHICH MAY DISTORT DIELECTRIC.



REMOVE DIELECTRIC TRIM TOOL AND CLEAN
ALL SURFACES THOROUGHLY.



SLIDE CLAMP NUT AND GASKET OVER
COPPER JACKET OF CABLE.





INSERT PREPARED CABLE TERMINATION INTO
CONNECTOR BODY. MAKE SURE COPPER JACKET
OF CABLE SEATS PROPERLY AGAINST
CONNECTOR BODY SHOULDER. TIGHTEN NUT TO
15-20 IN/LBS TORQUE, WHILE HOLDING BODY
STATIONARY.

Spec. No. 349-50114


ASSEMBLY PROCEDURE FOR FIELD SERVICEABLE SMA CONNECTOR

NO. 901-III




STRIPPING DIM'S SHOWN FOR REF. ONLY

TOOLS REQ'D.
KIT NO. 901-2500




TRIM CABLE SQUARE, DEBURR & CLEAN COPPER JACKET 5/8 MIN.




USING TOOL 901-A AND RAZOR BLADE, SCORE COPPER JACKET UNTIL BLADE BOTTOMS IN TOOL. RETRACT CABLE TO SCORE LINE. APPLY LIGHT BENDING FORCE ALTERNATELY UNTIL COPPER JACKET SEPARATES AT SCORE LINE AND REMOVE.


EXPOSED DIELECTRIC—




USING DIELECTRIC TRIM TOOL 901-C AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE DO NOT NICK CENTER CONDUCTOR.




FILE BLUNT END OF CENTER CONDUCTOR TO A 90° CONE.



REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY.




SLIDE CLAMP NUT AND GASKET OVER COPPER JACKET OF CABLE.



INSERT PREPARED CABLE TERMINATION INTO CONNECTOR BODY. MAKE SURE COPPER JACKET OF CABLE SEATS PROPERLY AGAINST CONNECTOR BODY SHOULDER. TIGHTEN NUT TO 15-20 IN./LB. TORQUE, WHILE HOLDING BODY STATIONARY.


Spec. No. 349-50114

ASSEMBLY PROCEDURE FOR FIELD SERVICEABLE SMA CONNECTORS




TOOLS REQ'D:
KIT NO. 901-2500


TOOL NO.	CONNECTOR
901-D	901-103, -104, -121 & -122.
901-8	901-257, -257-11 & 257-12.




PLACE NUT AND GASKET OVER CABLE AND CUT JACKET TO DIMENSION SHOWN.




COMB OUT BRAID AND FOLD OUT.




PULL BRAID WIRES FORWARD AND TAPER TOWARD CENTER CONDUCTOR. PLACE BRAID CLAMP OVER BRAID AND PUSH BACK AGAINST CABLE JACKET. FOLD BACK BRAID WIRES, TRIM AS NECESSARY SO THAT WIRES DO NOT TOUCH SHOULDER OF CLAMP.




USING DIELECTRIC TRIM TOOL, SEE TABLE ABOVE, AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE. DO NOT NICK CENTER CONDUCTOR. TIGHTEN NUT LIGHTLY. DO NOT DAMAGE GASKET.



SOLDER CENTER CONTACT TO CABLE. CENTER CONTACT MUST SEAT SQUARE AGAINST DIELECTRIC. AVOID EXCESSIVE HEAT, WHICH MAY DISTORT DIELECTRIC




REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY.




THREAD CONNECTOR ASSEMBLY ONTO PREPARED CABLE ASSEMBLY. TIGHTEN TO 20-25 IN./LBS. TORQUE.

ASSEMBLY PROCEDURE FOR CRIMP TYPE SMA CONNECTOR

NOS. 901-101, -102, -109, -110, -192, -152, 153, -246 & -200




SEE TABLE BELOW FOR PROPER CRIMPING TOOL.




SLIDE OUTER FERRULE ONTO CABLE AS SHOWN. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.



FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE. IMPORTANT: DO NOT COMB OUT BRAID.



SOLDER CENTER CONTACT TO CABLE. NOTE: CENTER CONDUCTOR SHOULD BE VISIBLE THROUGH SOFT SOLDER ACCESS HOLE IN CONTACT, PRIOR TO SOLDERING.





INSTALL BODY ONTO CABLE SO THAT FERRULE PORTION SLIDES UNDER BRAID AND INSULATOR BUTTS FLUSH AGAINST CABLE DIELECTRIC. SLIDE OUTER FERRULE OVER BRAID AND UP AGAINST BODY. MAKE SURE NO SLACK EXISTS IN BRAID. CRIMP OVER FERRULE WITH TOOL SPECIFIED IN TABLE, KEEPING CABLE DIELECTRIC BOTTOMED AGAINST INSULATOR.


PART NO.	A	B	C	AMPHENOL HEX CRIMP TOOLS FOR USE WITH RG-/U CABLE	AMPHENOL TOOL NO.	AMPHENOL DIE NO.	DIE CAVITY DESIGNATION
901-101 -102 -109 -110	$\frac{9}{32}$	$\frac{7}{64}$	$\frac{9}{64}$	55, 58, 141, 142, 223	227-944	227-1221-11	A
901-192	$\frac{9}{32}$	$\frac{5}{64}$	$\frac{3}{32}$	195, 180	227-944	227-1221-09	A
901-422, -423	$\frac{9}{32}$	$\frac{3}{32}$	$\frac{9}{64}$	174, 179, 187, 316		227-1221-03	
901-200	$\frac{9}{32}$	$\frac{7}{64}$	$\frac{3}{32}$	53	227-944	227-1221-13	A
901-3079, 82, 85, 88 80, 83, 86, 89 81, 84, 87,	$\frac{9}{32}$	$\frac{7}{64}$	$\frac{9}{64}$				

Spec. No. 349-50114


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTORS
FOR NOS. 901-126, 901-127, 901-151, 901-158, 901-193 & 901-195




TRIM CABLE SQUARE, DEBURR & CLEAN
COPPER JACKET 5/8 MIN.




USING TOOL 901-E AND RAZOR BLADE,
SCORE COPPER JACKET UNTIL BLADE BOTTOMS
IN TOOL. RETRACT CABLE TO SCORE LINE.
APPLY LIGHT BENDING FORCE ALTERNATELY
UNTIL COPPER JACKET SEPARATES AT
SCORE LINE AND REMOVE.




PLACE SOLDER NUT OVER CABLE; COPPER
JACKET MUST BOTTOM ON SHOULDER OF
SOLDER NUT. SOLDER AS SHOWN.




CAUTION-BEFORE TRIMMING DIELECTRIC,
ASSEMBLY MUST BE ALLOWED TO COOL.
USING DIELECTRIC TRIM TOOL 901-F
AND RAZOR BLADE, REMOVE EXPOSED
DIELECTRIC. CUT MUST BE SQUARE.
DO NOT NICK CENTER CONDUCTOR.



SOLDER CENTER CONTACT TO CABLE.
CENTER CONTACT MUST SEAT SQUARE
AGAINST DIELECTRIC. AVOID EXCESSIVE HEAT
WHICH MAY DISTORT DIELECTRIC.




REMOVE DIELECTRIC TRIM TOOL AND CLEAN
ALL SURFACES THOROUGHLY. INSTALL
GASKET AS SHOWN.




THREAD CONNECTOR ASSEMBLY ONTO
PREPARED CABLE ASSEMBLY. TIGHTEN
TO 15-25 IN./LBS. TORQUE.

ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-183




STRIPPING DIM'S SHOWN FOR REF. ONLY




TOOLS REQ'D: KIT NO. 901-2500.


REPAIR AND REPAIR KIT NO. 901-2500.



TRIM CABLE SQUARE, DEBURR AND CLEAN COPPER JACKET 5/8 MIN.




USING TOOL 901-A AND RAZOR BLADE, SCORE COPPER JACKET UNTIL BLADE BOTTOMS IN TOOL. RETRACT CABLE TO SCORE LINE. APPLY LIGHT BENDING ALTERNATELY UNTIL COPPER JACKET SEPARATES AT SCORE LINE AND REMOVE.




SOLDER

SLIDE COUPLING NUT ON CABLE. PLACE BODY ON CABLE. COPPER JACKET MUST BOTTOM ON SHOULDER OF BODY. SOLDER AS SHOWN. USE MINIMUM AMOUNT OF SOLDER AND CARE TO PREVENT SOLDER FLOWING OVER OUT SIDE OF BODY.



GASKET

CAUTION - BEFORE TRIMMING DIELECTRIC, ASSEMBLY MUST BE ALLOWED TO COOL. CUT DIELECTRIC SQUARE AND AS CLOSE TO BODY AS POSSIBLE AND REMOVE. DO NOT NICK CENTER CONDUCTOR. FILE BLUNT END OF CENTER CONDUCTOR TO A 90° CONE. INSTALL GASKET.





RETAINING RING

SLIDE NUT OVER BODY AND SNAP RETAINING RING IN PLACE.

Spec No. 349-50114

SHEET 9
CONT'D ON 10


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-136




STRIPPING DIM'S. SHOWN
FOR REF. ONLY
TOOLS REQ'D: KIT NO. 901-2500




TRIM CABLE SQUARE DEBURR AND CLEAN
COPPER JACKET 5/8 MIN.




USING TOOL 901-E AND RAZOR BLADE,
SCORE COPPER JACKET UNTIL BLADE BOTTOMS
IN TOOL. RETRACT CABLE TO SCORE LINE,
APPLY LIGHT BENDING FORCE ALTERNATELY
UNTIL COPPER JACKET SEPARATES AT
SCORE LINE AND REMOVE.




PLACE SOLDER NUT OVER CABLE; COPPER
JACKET MUST BOTTOM ON SHOULDER OF
SOLDER NUT. SOLDER AS SHOWN.



CAUTION - BEFORE TRIMMING DIELECTRIC,
ASSEMBLY MUST BE ALLOWED TO COOL.
USING DIELECTRIC TRIM TOOL 901-F
AND RAZOR BLADE, REMOVE EXPOSED
DIELECTRIC. CUT MUST BE SQUARE
DO NOT NICK CENTER CONDUCTOR.



REMOVE DIELECTRIC TRIM TOOL AND CLEAN
ALL SURFACES THOROUGHLY. INSTALL
GASKET AS SHOWN





THREAD CONNECTOR ASSEMBLY ONTO
PREPARED CABLE ASSEMBLY. TIGHTEN
TO 15-25 IN./LBS. TORQUE AND
SOLDER CENTER CONDUCTOR AND CAP
IN PLACE.


SPEC. 349-50114 SHEET 10

SHEET 10 CONT'D ON 11


ASSEMBLY PROCEDURE FOR FIELD SERVICEABLE SMA CONNECTORS NOS. 901-128, -173, -174, -139, -129, -220, -281, -283, -256, -246




CUT JACKET TO DIMENSION SHOWN.




COMB OUT BRAID AND FOLD OUT.




PULL BRAID WIRES FORWARD AND TAPER TOWARD CENTER CONDUCTOR. PLACE CLAMP NUT ASS'Y. OVER BRAID AND PUSH BACK AGAINST CABLE JACKET. FOLD BACK BRAID WIRES, TRIM AS NECESSARY SO THAT WIRES DO NOT TOUCH SHOULDER OF GASKET.



SCREW TRIM TOOL (SEE TABLE BELOW) ONTO CLAMP NUT ASSEMBLY. TIGHTEN NUT LIGHTLY. DO NOT DAMAGE GASKET. USING RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE. DO NOT NICK CENTER CONDUCTOR.



REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY. ASSEMBLE BUSHING ASSEMBLY AND SOLDER CENTER CONTACT TO CABLE.




THREAD CONNECTOR ASSEMBLY ONTO PREPARED CABLE ASSEMBLY. TIGHTEN TO 20-25 IN./LBS. TORQUE.


TOOL NO.	CONNECTOR
901-G	901-128, -173, -174, -129
901-3	901-139, -220, 246
901-6	901-281, -283 & -256

SPEC. 349-50114 SHEET 11


ASSEMBLY PROCEDURE FOR FIELD SERVICEABLE SMA CONNECTORS NOS. 901-140, -172, & -287, 367, 368




OPTIONAL
TOOLS REQ'D:
KIT NO. 901-2500.




CUT JACKET TO DIMENSION SHOWN.




COMB OUT BRAID AND FOLD OUT.




PULL BRAID WIRES FORWARD AND TAPER TOWARD CENTER CONDUCTOR. PLACE CLAMP NUT ASS'Y. OVER BRAID AND PUSH BACK AGAINST CABLE JACKET. FOLD BACK BRAID WIRES, TRIM AS NECESSARY SO THAT WIRES DO NOT TOUCH SHOULDER OF GASKET.



USING DIELECTRIC TRIM TOOL (SEE TABLE BELOW) AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE. DO NOT NICK CENTER CONDUCTOR. TIGHTEN NUT LIGHTLY. DO NOT DAMAGE GASKET.





REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY.
OR
TRIM DIELECTRIC & CENTER CONDUCTOR TO DIMENSIONS SHOWN




THREAD CONNECTOR ASSEMBLY ONTO PREPARED CABLE ASSEMBLY. TIGHTEN TO 14-16 IN./LBS. TORQUE AND SOLDER CENTER CONDUCTOR AND CAP IN PLACE.

CONNECTOR	TOOL NO.
901-140, 172, 287 & 368	901-5
901-367	901-7


ASSEMBLY PROCEDURE FOR FIELD SERVICEABLE SMA CONNECTOR
NO. 901-130, 901-369, -370




TOOLS REQ'D:
KIT NO. 901-2500.




PLACE NUT AND GASKET OVER CABLE AND CUT JACKET TO DIMENSION SHOWN.




COMB OUT BRAID AND FOLD OUT.




PULL BRAID WIRES FORWARD AND TAPER TOWARD CENTER CONDUCTOR PLACE BRAID CLAMP OVER BRAID AND PUSH BACK AGAINST CABLE JACKET. FOLD BACK BRAID WIRES, TRIM AS NECESSARY SO THAT WIRES DO NOT TOUCH SHOULDER OF CLAMP.



USING DIELECTRIC TRIM TOOL 901-4 AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE. DO NOT NICK CENTER CONDUCTOR. TIGHTEN NUT LIGHTLY. DO NOT DAMAGE GASKET.





REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY.



THREAD CONNECTOR ASSEMBLY ONTO PREPARED CABLE ASSEMBLY TIGHTEN TO 15-18 IN./LBS. TORQUE AND SOLDER CENTER CONDUCTOR AND CAP IN PLACE.


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-142




STRIPPING DIM'S. SHOWN FOR REF. ONLY
TOOLS REQ'D: KIT NO. 901-2500




TRIM CABLE SQUARE DEBURR AND CLEAN COPPER JACKET 5/8 MIN.




USING TOOL 901-A AND RAZOR BLADE, SCORE COPPER JACKET UNTIL BLADE BOTTOMS IN TOOL. RETRACT CABLE TO SCORE LINE, APPLY LIGHT BENDING FORCE ALTERNATELY UNTIL COPPER JACKET SEPARATES AT SCORE LINE AND REMOVE.




PLACE SOLDER NUT OVER CABLE; COPPER JACKET MUST BOTTOM ON SHOULDER OF SOLDER NUT. SOLDER AS SHOWN.



CAUTION - BEFORE TRIMMING DIELECTRIC, ASSEMBLY MUST BE ALLOWED TO COOL. USING DIELECTRIC TRIM TOOL 901-B AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE DO NOT NICK CENTER CONDUCTOR.



REMOVE DIELECTRIC TRIM TOOL AND CLEAN ALL SURFACES THOROUGHLY. INSTALL GASKET AS SHOWN




THREAD CONNECTOR ASSEMBLY ONTO PREPARED CABLE ASSEMBLY. TIGHTEN TO 15-25 IN./LBS. TORQUE AND SOLDER CENTER CONDUCTOR AND CAP IN PLACE.


SPEC. 349-50114 SHEET 14

SHEET 14 CONT'D. ON 15


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR
NO. 901-273




FOR USE WITH .250 CUJAK CABLE



TRIM CABLE SQUARE. CLEAN
COPPER JACKET 5/8 MIN.





TRIM JACKET AND DIELECTRIC TO
DIMENSION SHOWN. CUT MUST BE
SMOOTH AND SQUARE. DO NOT NICK
CENTER CONDUCTOR. POINT CENTER
CONDUCTOR AS SHOWN. REMOVE BURRS.



INSERT CABLE. JACKET MUST BUTT
FIRMLY AGAINST SHOULDER OF
CONNECTOR. MAINTAIN END PRESSURE
WHILE SOLDERING. CAUTION-AVOID
OVERHEATING.


ASSEMBLY PROCEDURE FOR CRIMP TYPE SMA CONNECTOR NO. 901-155

INNER FERRULE, CONTACT GASKET, CLAMP NUT ASS'Y.




SLIDE HEAT SHRINK TUBING AND OUTER FERRULE ONTO CABLE. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.


CONNECTOR	A	B	C	TOOL & DIE
901-155	7/32	11/32	1/8	TOOL 227-944
901-155-16	9/32	7/64	9/64	DIE SET 227-1221-03
901-156				
901-476				
901-109-15	9/32	7/64	9/64	TOOL 227-944 DIE SET 227-1221-11




FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE, CONTACT ASSEMBLY. IMPORTANT: DO NOT COMB OUT BRAID.



INSTALL FERRULE-CONTACT ASS'Y. ONTO CABLE. SOLDER CENTER CONTACT TO CABLE. NOTE CENTER CONDUCTOR SHOULD BE VISIBLE THROUGH SOLDER ACCESS HOLE IN CONTACT, PRIOR TO SOLDERING. CABLE MUST BUTT FIRMLY AGAINST CONTACT WHILE SOLDERING. FLANKS OF CENTER CONTACT SOLDERING REQUIRED.





SLIDE OUTER FERRULE IN PLACE AND CRIMP WITH THOMAS & BETTS TOOL PER ABOVE TABLE




SCREW FERRULE-CONTACT ASSEMBLY INTO BODY AND TIGHTEN TO 20-25 IN./LBS. TORQUE. SLIDE HEAT SHRINK TUBING OVER FERRULE, UP AGAINST CLAMP NUT AND APPLY HEAT.


ASSEMBLY PROCEDURE FOR CRIMP TYPE SMA CONNECTOR NO. 901-360




SLIDE HEAT SHRINK TUBING AND OUTER FERRULE ONTO CABLE AS SHOWN. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.




FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE. IMPORTANT: DO NOT COMB OUT BRAID.



SOLDER CENTER CONTACT TO CABLE. NOTE: CENTER CONDUCTOR SHOULD BE VISIBLE THROUGH SOFT SOLDER ACCESS HOLE IN CONTACT, PRIOR TO SOLDERING.





INSTALL BODY ONTO CABLE SO THAT FERRULE PORTION SLIDES UNDER BRAID AND INSULATOR BUTTS FLUSH AGAINST CABLE DIELECTRIC. SLIDE OUTER FERRULE OVER BRAID AND UP AGAINST BODY. MAKE SURE NO SLACK EXISTS IN BRAID. SOLDER THRU ACCESS HOLE SO THAT BODY, BRAID AND FERRULE ARE SECURELY ATTACHED.




SLIDE HEAT SHRINK TUBING UP AGAINST SHOULDER OF BODY AND APPLY MODERATE HEAT.


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-361




SLIDE HEAT SHRINK TUBING AND OUTER FERRULE ONTO CABLE AS SHOWN. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.



FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE. IMPORTANT: DO NOT COMB OUT BRAID.





INSTALL BODY ONTO CABLE SO THAT FERRULE SLIDES UNDER BRAID. CENTER CONDUCTOR SHOULD OCCUPY SLOT IN CENTER CONTACT BUT NOT PROTRUDE ABOVE. DIELECTRIC SHOULD EXTEND APPROX. 1/64 INTO CAVITY. SOLDER CENTER CONDUCTOR TO CONTACT. SOLDER THRU ACCESS HOLE IN FERRULE SO THAT IT IS SECURELY ATTACHED TO BRAID AND BODY. SOLDER CAP TO BODY.




SLIDE HEAT SHRINK TUBING UP AGAINST SHOULDER OF BODY AND APPLY MODERATE HEAT.

ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-390




STRIPPING DIM'S SHOWN FOR REF. ONLY


TOOLS REQ'D: 901-A & 901-8




TRIM CABLE SQUARE, DEBURR AND CLEAN COPPER JACKET 5/8 MIN.




USING TOOL 901-A AND RAZOR BLADE, SCORE COPPER JACKET UNTIL BLADE BOTTOMS IN TOOL. RETRACT CABLE TO SCORE LINE. APPLY LIGHT BENDING ALTERNATELY UNTIL COPPER JACKET SEPARATES AT SCORE LINE AND REMOVE.



USING DIELECTRIC TRIM TOOL 901-8 AND RAZOR BLADE, REMOVE EXPOSED DIELECTRIC. CUT MUST BE SQUARE. DO NOT NICK CENTER CONDUCTOR.




CUT CENTER CONTACT TO LENGTH AND POINT AS SHOWN.




INSERT PREPARED CABLE INTO CONNECTOR ASSEMBLY. CENTER CONDUCTOR MUST ENTER SOCKET IN CENTER CONTACT, PRESS IN FIRMLY AND SOLDER. AVOID EXCESSIVE HEAT WHICH MAY DISTORT DIELECTRIC.

ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NO. 901-390




901-390 COMPLETE ASSEMBLY
(PLUG)




TOOLS REQ'D: TOOL NO. 901-E
FROM AMPHENOL TOOL KIT
NO. 901-2500




TRIM CABLE SQUARE, DEBURR AND CLEAN
COPPER JACKET 5/8 MIN.



USING TOOL 901-E AND RAZOR BLADE,
SCORE COPPER JACKET UNTIL BLADE
BOTTOMS IN TOOL. RETRACT CABLE TO
SCORE LINE. APPLY LIGHT BENDING
ALTERNATELY UNTIL COPPER JACKET
SEPARATES AT SCORE LINE AND REMOVE.




TRIM DIELECTRIC EVEN WITH JACKET
DO NOT NICK CENTER CONDUCTOR.
CUT CENTER CONDUCTOR TO LENGTH
SHOWN AND POINT END APPROXIMATELY
60°.




SLIDE SOLDER RING OVER CABLE.
INSERT CABLE INTO CONNECTOR.
MAKE SURE CENTER CONDUCTOR IS
STRAIGHT. USE CARE IN PUSHING
CENTER CONDUCTOR INTO SPRING
CONTACT. MAKE SURE JACKET
BOTTOMS IN CONNECTOR. MAINTAIN
END PRESSURE WHILE SOLDERING.
AVOID EXCESSIVE HEAT WHICH
MAY DISTORT DIELECTRIC.


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR
 NOS. 901-339, -340, -342, -408.




TOOLS REQ'D.
 901-E FOR .085 CUJAK CABLE
 901-A FOR .141 CUJAK CABLE
 FROM TOOL KIT 901-2500.




TRIM CABLE SQUARE, DEBURR AND CLEAN
 COPPER JACKET 5/8 MIN.




USING TOOL 901-A OR 901-E AND RAZOR
 BLADE, SCORE COPPER JACKET UNTIL BLADE
 BOTTOMS IN TOOL. RETRACT CABLE TO SCORE
 LINE. APPLY LIGHT BENDING ALTERNATELY
 UNTIL COPPER JACKET SEPARATES AT SCORE
 LINE AND REMOVE.



CUT DIELECTRIC BACK EVEN WITH
 JACKET. DO NOT NICK CENTER
 CONDUCTOR. CUT CENTER CONDUCTOR
 TO DIMENSION SHOWN.




SOLDER CENTER CONTACT TO CENTER
 CONDUCTOR. USE .015 SHIM TO MAINTAIN
 SPACE ACCURATELY BETWEEN CONTACT
 AND JACKET.




INSERT CABLE INTO CONNECTOR ASSEMBLY
 MAKE SURE JACKET BOTTOMS IN
 CONNECTOR. MAINTAIN END PRESSURE
 WHILE SOLDERING. AVOID EXCESSIVE
 HEAT WHICH MAY DISTORT DIELECTRIC.


ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR NOS. 901-380, -381, -386




TOOLS REQ'D.
901-E FOR .085 CUJAK CABLE
901-A FOR .141 CUJAK CABLE
FROM TOOL KIT 901-2500.




TRIM CABLE SQUARE, DEBURR AND CLEAN
COPPER JACKET 5/8 MIN.




USING TOOL 901-A OR 901-E AND RAZOR
BLADE, SCORE COPPER JACKET UNTIL BLADE
BOTTOMS IN TOOL. RETRACT CABLE TO SCORE
LINE. APPLY LIGHT BENDING ALTERNATELY
UNTIL COPPER JACKET SEPARATES AT SCORE
LINE AND REMOVE.



CUT DIELECTRIC BACK EVEN WITH
JACKET. DO NOT NICK CENTER
CONDUCTOR. CUT CENTER CONDUCTOR
TO DIMENSION SHOWN.




SOLDER CENTER CONTACT TO CENTER
CONDUCTOR. USE .015 SHIM TO MAINTAIN
SPACE ACCURATELY BETWEEN CONTACT
AND JACKET.





INSERT CABLE INTO CONNECTOR ASSEMBLY
MAKE SURE JACKET BOTTOMS IN
CONNECTOR. MAINTAIN END PRESSURE
WHILE SOLDERING. AVOID EXCESSIVE
HEAT WHICH MAY DISTORT DIELECTRIC.

ASSEMBLY PROCEDURE FOR SOLDER TYPE SMA CONNECTOR 901-9005




TOOLS REQ'D.
901-E FOR .086 RG-405/U CABLE


ASSEMBLY PROCEDURE FOR CRIMP TYPE SMA CONNECTOR 901-3090; 3091; 3092



SLIDE HEAT SHRINK TUBING AND OUTER FERRULE ONTO CABLE AS SHOWN. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.




FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE. IMPORTANT: DO NOT COMB OUT BRAID.



INSTALL BODY ONTO CABLE SO THAT FERRULE SLIDES UNDER BRAID. CENTER CONDUCTOR SHOULD OCCUPY SLOT IN CENTER CONTACT BUT NOT PROTRUDE ABOVE. CRIMP FERRULE WITH PROPER TOOL. (SEE CHART BELOW) SOLDER CENTER CONDUCTOR TO CONTACT.

SOLDER CAP TO BODY. DO NOT USE EXCESSIVE HEAT.




SLIDE HEAT SHRINK TUBING UP AGAINST SHOULDER OF BODY AND APPLY MODERATE HEAT.

PART NO	AMPHENOL HEX CRIMP TOOL FOR RG-7/8 CABLE	AMPHENOL TOOL NO	AMPHENOL DIE NO	DIE CAVITY
901-3090	58,55,141,142,223	227-944	227-1221-11	A
901-3091	180,195	227-944	227-1221-09	A
901-3092	316,174,179,187	227-944	227-1221-03	A
SPEC. NO. 349-50114				
SHEET NO. 25 CONT'D ON 26				


ASSEMBLY PROCEDURE FOR CRIMP TYPE SMA CONNECTOR

NO. 901-3073; 3074; 3075; 3076; 3077; 3078.


- SMA JACK




SEE TABLE BELOW FOR PROPER CRIMPING TOOL.



SLIDE HEAT SHRINK TUBING AND OUTER FERRULE ONTO CABLE AS SHOWN. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC, OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.




FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE. IMPORTANT: DO NOT COMB OUT BRAID.




SOLDER ACCESS HOLE

SOLDER CENTER CONTACT TO CABLE. NOTE: CENTER CONDUCTOR SHOULD BE VISIBLE THROUGH SOFT SOLDER ACCESS HOLE IN CONTACT, PRIOR TO SOLDERING.



INSTALL BODY ONTO CABLE SO THAT FERRULE PORTION SLIDES UNDER BRAID AND INSULATOR BUTTS FLUSH AGAINST CABLE DIELECTRIC. SLIDE OUTER FERRULE OVER BRAID AND UP AGAINST BODY. MAKE SURE NO SLACK EXISTS IN BRAID. CRIMP FERRULE WITH PROPER CRIMP TOOL.



SLIDE HEAT SHRINK TUBING UP AGAINST SHOULDER OF BODY AND APPLY MODERATE HEAT.


AMPHENOL HEX CRIMP TOOL FOR USE WITH RG/U CABLE
55, 58, 141, 142, 223
180, 195
316, 174, 179, 187

AMPHENOL TOOL NO
227-944
227-944
227-944


AMPHENOL DIE NO
227-1221-11
227-1221-09
227-1221-03

DIE CAVITY
A
A
A

ASSEMBLY PROCEDURE FOR CRIMP TYPE SMA CONNECTOR
 NOS. 901-B-5503-2075




SEE TABLE BELOW
 FOR PROPER
 CRIMPING TOOL.




SLIDE OUTER FERRULE ONTO CABLE AS SHOWN. STRIP CABLE JACKET, BRAID AND DIELECTRIC TO DIMENSIONS SHOWN. ALL CUTS ARE TO BE SHARP AND SQUARE. IMPORTANT: DO NOT NICK BRAID, DIELECTRIC OR CENTER CONDUCTOR WHEN CUTTING. TIN CENTER CONDUCTOR. AVOID EXCESSIVE HEAT TO PREVENT SWELLING OF CABLE DIELECTRIC.



FLARE END OF CABLE BRAID SLIGHTLY AS SHOWN TO FACILITATE INSERTION ONTO INNER FERRULE. IMPORTANT: DO NOT COMB OUT BRAID.



SOLDER CENTER CONTACT TO CABLE. NOTE: CENTER CONDUCTOR SHOULD BE VISIBLE THROUGH SOFT SOLDER ACCESS HOLE IN CONTACT, PRIOR TO SOLDERING.



INSTALL BODY ONTO CABLE SO THAT FERRULE PORTION SLIDES UNDER BRAID AND INSULATOR BUTTS FLUSH AGAINST CABLE DIELECTRIC. SLIDE OUTER FERRULE OVER BRAID AND UP AGAINST BODY. MAKE SURE NO SLACK EXISTS IN BRAID. CRIMP OVER FERRULE WITH TOOL SPECIFIED BELOW, KEEPING CABLE DIELECTRIC BOTTOMED AGAINST INSULATOR.

HEX CRIMP SIZE	AMPHENOL TOOL No.	AMPHENOL DIE No.	DIE CAVITY DESIGNATION
.128	227-944	227-1221-03	A